
PR₂PR₃

Accessories Guide

FlexDock and Charging Options

Docking System	Part Number	Description
	DX2A27700	Two-bay FlexDock, charge only. For the PR2/PR3. No power cord.
	DX2A27710	Two-bay FlexDock, charge only. For the PR2/PR3. North American power cord.


All configurations include dock base, adapter cups, power supply, and are fully assembled. North America configurations include US AC line cord. International configurations require country-specific line cord, ordered separately.



All configurations include dock base, adapter cups, power supply, and are fully assembled. North America configurations include US AC line cord. International configurations require country-specific line cord, ordered separately.

DX2A2FF10	4-pos Battery Charger PR2/3 North American Power Cord
DX2A2FF00	4-pos Battery Charger PR2/3 No Power Cord

All configurations include dock base, adapter cups, power supply, and are fully assembled. North America configurations include US AC line cord. International configurations require country-specific line cord, ordered separately.



All configurations include dock base, adapter cups, power supply, and are fully assembled. North America configurations include US AC line cord. International configurations require country-specific line cord, ordered separately.

include US AC line cord. Internat	ional configurations require count	try-specific line cord, ordered separately.
F. 4 4550 A	203-965-001	FlexDock battery pack charging
		cup for use with the 4-bay or 2-bay flex dock. PR2 or PR3.
		·
	203-964-001	FlexDock Mobile Printer cup for
		PR2/3 Mobile printer. For use with the 2-bay or 4-bay flex dock.
-		, ,
	852-916-001	FlexDock Base Quad Charge Only
minimized and		
and and and	852-917-001	FlexDock Base Quad Ethernet
	852-919-001	FlexDock Base Dual Ethernet
	852-920-001	FlexDock Base Desktop



All configurations include dock base, adapter cups, power supply, and are fully assembled. North America configurations include US AC line cord. International configurations require country-specific line cord, ordered separately.

PR₂PR₃

Accessories Guide

Charging and Power

Accessory Name

Batteries and Charging Options	318-049-001	Standard Battery Pack, 7.4V 1.62Ah
	318-050-001	Smart Battery Pack PR2/PR3,7.4V,1.62Ah
P	852-043-004	Cigarette lighter Power Adapter, RoHS
AC Power Cord - 3 Prong	071918	AC Power Cord, China RoHS
	1-974027-025	AC Power Cord, Europe RoHS
	1-974028-025	AC Power Cord, US RoHS
	1-974029-020	AC Power Cord, UK RoHS
	1-974030-025	AC Power Cord, Australia RoHS
	321-471-002	AC Power Cord, Italy RoHS
	321-500-002	AC Power Cord, Japan RoHS
	321-501-002	AC Power Cord, Denmark RoHS
	321-502-002	AC Power Cord, India/S Africa RoHS

Description

Part Number

Belt Clips and Belt Loops

Accessory	Part Number	Description
Terr .	825-227-001	Plastic belt clip for the PR2 and PR3.
	825-226-001	Metal belt clip for the PR2 and PR3.
	825-225-001	Belt Loop PR2/3.
	BL-701-102	Vocollect Belt Clip for use with Belt Loop 825-225-001



Accessory	Part Number	Description
	203-996-001	PR2 Protective Boot.
	203-997-001	PR3 Protective Boot.
	825-222-001	PR2 Protective Case (Environmental case). Ships with shoulder strap.
	825-223-001	PR3 Protective Case (Environmental case). Ships with shoulder strap.



© 2013 Honeywell International Inc. 612186-B 10/13